



IRA PERFORMANCE DATA

Face Velocity			300	400	500	600	700
Sizes	Free area(sq.in)						
06X04 Ak 0.111	17	CFM Ps	35 0.010	47 0.018	57 0.030	67 0.041	72 0.056
06X06 Ak 0.167	24	CFM Ps	51 0.010	68 0.018	87 0.030	102 0.041	119 0.056
08x04 Ak 0.148	22	CFM Ps	45 0.010	60 0.018	75 0.030	90 0.041	105 0.056
08x06 Ak 0.223	33	CFM Ps	69 0.010	89 0.018	113 0.030	135 0.041	157 0.056
08x08 Ak 0.299	45	CFM Ps	91 0.010	120 0.018	152 0.029	180 0.041	210 0.056
10x04 Ak 0.185	28	CFM Ps	57 0.010	75 0.018	95 0.030	112 0.041	132 0.056
10x06 Ak 0.28	44.000	CFM Ps	86 0.010	114 0.018	142 0.030	170 0.041	198 0.056
10x08 Ak 0.375	58	CFM Ps	115 0.010	155 0.018	189 0.029	227 0.041	264 0.056
10x10 Ak 0.470	74	CFM Ps	143 0.010	190 0.018	238 0.030	284 0.041	332 0.056
12x06 0.337	52	CFM Ps	103 0.010	139 0.018	171 0.030	205 0.041	239 0.056
12x08 Ak 0.451	70	CFM Ps	137 0.010	182 0.018	228 0.029	275 0.041	318 0.056
12x10 Ak 0.566	90	CFM Ps	172 0.010	228 0.018	285 0.030	342 0.041	398 0.056
12x12 Ak 0.681	108	CFM Ps	200 0.010	274 0.018	342 0.030	410 0.041	478 0.056
14x06 Ak 0.394	62	CFM Ps	120 0.010	160 0.018	200 0.030	238 0.041	278 0.056
14x08 Ak 0.527	84	CFM Ps	160 0.010	213 0.018	268 0.030	318 0.041	361 0.056
14x10 Ak 0.661	106	CFM Ps	200 0.010	268 0.018	333 0.030	401 0.041	465 0.056
14x14 Ak 0.93	148	CFM Ps	282 0.010	375 0.018	468 0.030	560 0.041	654 0.056
16x06 Ak 0.451	72	CFM Ps	138 0.010	184 0.018	230 0.030	275 0.041	318 0.056
16x08 Ak 0.604	98	CFM Ps	184 0.010	245 0.018	305 0.030	365 0.041	425 0.056
16x10 Ak 0.757	122	CFM Ps	230 0.010	307 0.018	382 0.030	458 0.041	534 0.056
16x12 Ak 0.911	146	CFM Ps	275 0.010	370 0.018	458 0.029	550 0.041	641 0.056
16x16 Ak 1.219	196	CFM Ps	368 0.010	490 0.018	612 0.030	734 0.041	856 0.056
18x06 Ak 0.508	78	CFM Ps	155 0.010	205 0.018	256 0.030	308 0.041	359 0.057
18x18 Ak 1.548	244	CFM Ps	470 0.010	623 0.018	778 0.030	932 0.041	1086 0.057



20x06		CFM	174	230	294	342	400
Ak 0.566	86	Ps	0.010	0.018	0.030	0.041	0.056
20x10		CFM	289	384	479	574	669
Ak 0.949	146	Ps	0.010	0.018	0.030	0.041	0.056
20x12		CFM	346	460	574	670	804
Ak 1.142	176	Ps	0.010	0.018	0.030	0.041	0.056
20x14		CFM	404	538	672	805	940
Ak 1.335	206	Ps	0.010	0.018	0.030	0.041	0.056
20x20		CFM	579	771	964	1154	1648
Ak 1.917	296	Ps	0.010	0.018	0.030	0.041	0.057
20x24		CFM	694	925	1157	1386	1618
Ak 2.307	356	Ps	0.010	0.018	0.030	0.041	0.057
20x25		CFM	726	968	1206	1442	1688
Ak 2.404	372	Ps	0.010	0.018	0.030	0.041	0.057
24x04		CFM	139	184	230	275	320
Ak .451	68	Ps	0.010	0.018	0.030	0.041	0.057
24x06		CFM	206	274	344	412	480
Ak .681	104	Ps	0.010	0.018	0.030	0.041	0.056
24x08		CFM	275	370	459	551	642
Ak .911	142	Ps	0.010	0.018	0.030	0.041	0.056
24x10		CFM	345	460	574	689	804
Ak 1.142	178	Ps	0.010	0.018	0.030	0.041	0.056
24x12		CFM	416	554	691	829	966
Ak 1.374	214	Ps	0.010	0.018	0.030	0.041	0.056
24x14		CFM	484	646	805	970	1129
Ak 1.607	252	Ps	0.010	0.018	0.030	0.041	0.056
24x24		CFM	834	1115	1391	1670	1946
Ak 2.775	434	Ps	0.010	0.018	0.030	0.041	0.056
30x04		CFM	174	230	291	341	400
Ak 0.566	84	Ps	0.010	0.018	0.030	0.041	0.056
30x06		CFM	260	345	431	516	601
Ak 0.853	130	Ps	0.010	0.018	0.030	0.041	0.057
30x08		CFM	345	461	576	689	804
Ak 1.142	176	Ps	0.010	0.018	0.030	0.041	0.056
30x10		CFM	435	581	720	864	1008
Ak 1.432	224	Ps	0.010	0.018	0.030	0.041	0.056
30x12		CFM	522	693	866	1038	1210
Ak 1.723	268	Ps	0.010	0.018	0.030	0.041	0.056
30x14		CFM	610	810	1010	1212	1414
Ak 2.015	314	Ps	0.010	0.018	0.030	0.041	0.056
30x20		CFM	870	1162	1450	1740	2029
Ak 2.892	452	Ps	0.010	0.018	0.030	0.041	0.057
30x24		CFM	1050	1398	1746	2092	2440
Ak 3.479	544	Ps	0.010	0.018	0.030	0.041	0.057
30x30		CFM	1314	1749	2185	2622	3060
Ak 4.363	680	Ps	0.010	0.018	0.030	0.041	0.057
36x06		CFM	312	414	517	620	722
Ak 1.1027	156	Ps	0.010	0.018	0.030	0.041	0.057
30x08		CFM	415	554	694	829	968
Ak1.374	212	Ps	0.010	0.018	0.030	0.041	0.056